

FY90-1462

**SITE ASSESSMENT REPORT**

**For**

*TXD174127407*

**Hi-Tech Plating Facility A.K.A.  
Abandoned Electroplating Facility  
Balch Springs, Dallas County, Texas**

**Prepared for**

**EPA - REGION VI  
EMERGENCY RESPONSE BRANCH**

**J. Chris Petersen  
Deputy Project Officer**

**By**

**Ecology and Environment, Inc.  
Technical Assistance Team**

**30 June 1990**



**ecology and environment, inc.**

1509 MAIN STREET, SUITE 814, DALLAS, TEXAS 75201, TEL. 214-742-6601

International Specialists in the Environment

recycled paper



960150



# ecology and environment, inc.

1509 MAIN STREET, SUITE 814, DALLAS, TEXAS 75201, TEL. 214-742-6601

International Specialists in the Environment

FY90-1462

Date: 30 June 1990

To: James Staves, OSC  
EPA Region VI, Emergency Response Branch

Thru: J. Chris Petersen, DPO  
EPA Region VI, Emergency Response Branch

Thru: Kishor Fruitwala, TATL  
Region VI, Technical Assistance Team

From: Henry Liserio  
Region VI, Technical Assistance Team

Subj: Site Assessment Report:  
Hi-Tech Plating Facility  
A.K.A. Abandoned Electroplating Facility  
Balch Springs, Dallas County, Texas  
TDD# T06-9002-35  
PAN# TTX1100SAA

## PURPOSE

On 28 February and 1-2 March 1990, at approximately 1430 hours, Region VI Technical Assistance Team (TAT) members Henry Liserio and Tom Yank conducted a site assessment at the Hi-Tech Plating facility located at 2017 Peachtree Road in Balch Springs, Dallas County, Texas.

The TAT was tasked to evaluate the potential for an immediate removal action, photodocument the area of the reported corrosive spill, measure pH in any pools found in the drainage ditch, conduct air monitoring, and investigate and tentatively identify the contents of the plating vats inside the facility building.

## BACKGROUND

The site assessment was conducted in response to an anonymous citizen's complaint to the EPA Emergency Response Branch on 28 February 1990 of acids and other corrosive materials leaking from an abandoned plating facility at 2017 Peachtree Road in Balch Springs, Dallas County, Texas (Attachment A). The property on which the facility is located is owned by Mr. Edwin Brown of Troup, Texas. The property was leased to Mr. Reggie Gist, who operated a metal plating facility under the business name: Hi-Tech Plating. According to Mr. Bob Grant, Fire Chief for Balch

Springs Fire Department, Mr. Gist terminated the plating operations and abandoned the building in approximately early February of 1990. Mr. Grant stated that a corrosive material had leaked out from one of the large plating vats, stored at the south end the building, into a nearby drainage ditch (Attachment sand berms around the building, and pouring sand on the spilled material. Mr. Grant informed TAT that approximately 54 vats containing highly acidic and basic waste liquids and sludges were located inside the building. The fire department officials observed that some of the vats were leaking and attempted to stop a substantial leak from one of the vats by using a wooden bung. The officials have also encountered young trespassers who entered the facility through an opening in the south sheet metal wall which was corroded by the leaking material.

On 1 March 1990, Mr. Paul Cooper of the Texas Water Commission(TWC) informed TAT that the facility was being investigated by officials of the TWC and the RCRA branch of the EPA for illegal discharge of cyanide and metal wastes into the sewer lines. The sewer lines from the facility were removed by the City of Balch Springs Water Department after numerous attempts to control the discharges of cyanide and metal wastes via the sewer line into the municipal water treatment plant had failed.

According to Fire Chief, Mr. Grant, the site owner( Mr. Brown) was in the process of receiving bids from several clean-up contractors to remediate and stabilize the threats posed by the site wastes.

#### OBSERVATIONS

The site is readily accessible from nearby Peachtree Road and is surrounded by occupied buildings and businesses located within 25 feet of the facility . Upon arrival at the site on 28 February 1990 at 1430 hours , TAT observed sanded material near the south wall of the site and along a pathway through the site parking lot to a drainage ditch on the southeast corner of the site (Photos # 2 & 3). Dead vegetation was observed in the drainage area where the flow entered the drainage ditch. TAT also observed a green discoloration near the sanded material, and part of the concrete foundation near the sanded portion of the building was corroded (Photos # 5 & 6). The bottom of the north wall also had openings which appeared to be caused by the leaking material (Photo # 8).

Approximately 15 fifty-five gallon drums labeled as containing hydrochloric acid and aluminum etch were located outside the north wall of the building (Photos # 9 & 10) . A majority of the drums seemed to contain large amounts of products or wastes and were unopened.

On 1 March 1990, TAT assessed each of the 54 vats inside the

building by measuring the physical dimensions , the approximate volume of wastes , and the pH of the wastes in each vat (Attachment C). A majority of the vat wastes had a pH, measured with indicator strips, of 0 to 2 and 12 to 14. Several vats containing highly acidic and basic wastes were located adjacent to each other, and some were almost full with minimal freeboard (less than 4 inches). All of the vats were open surface tanks with no coverings. A large percentage of the vats were in poor condition and visibly corroded, with several of the vats leaking. The approximate volume of the acidic wastes (pH 0 to 2) was 28,000 gallons, and the basic materials (pH 12-14) was 20,000 gallons.


Several liquid samples collected by the TAT from three vats that had a pH above 13 were screened for cyanide by using a silver nitrate reagent. Of the three vats, two samples revealed a positive indication for cyanide. One of the vats (confirmed as containing cyanide) was located adjacent to a vat containing highly acidic wastes.

In addition, the TAT conducted air monitoring inside the building with the following instruments: HNU photoionization unit, explosimeter, MIRAN infrared analyzer and drager tubes for HCN, acid vapors, HCl, and cyanide compounds. The MIRAN infrared analyzer consistently detected HCN vapors ranging from 5 to 8 ppm near the vats located on the northern end of the building (near the vats confirmed as containing cyanide). The acid drager tubes detected approximately 3 to 5 ppm of acid vapors ambient air of the building, and the cyanide drager tubes detected 3 to 6 ppm of cyanides above the headspace of several of the vats (Attachment D).

Upon completion of the site assessment, a meeting was arranged with management officials of the Emergency Response Branch and Criminal Investigation Division of the EPA to discuss the potential for an immediate removal action. The site owner was contacted by the On-Scene Coordinator to discuss the immediate threats posed by the site and the possible need for immediate stabilization actions .


**ATTACHMENTS:**


- A. Site Location Map
- B. Site Sketch
- C. Vat Inventory for Hi-Tech Plating (2 pages)
- D. Air Monitoring Results for Hi-Tech Plating Facility (1 page)
- E. Mounted Photographs ( 5 pages)
- F. Unused Photographs and Negatives
- G. POLREPs (3 pages)
- H. Records of Communication (6 pages)
- I. Copies of Logbook Pages (1-29)
- J. Copy of TDD # T06-9002-35 and Amendments A,B



**LOCATION MAP**  
**ABANDONED ELECTROPLATING FACILITY**  
**BALCH SPRINGS, DALLAS COUNTY, TX**

SCALE 1:24,000





Ecology and Environment, Inc.  
Technical Assistance Team  
Region VI

Case: FY90-1462	TDD: T06-9002-35
Pan: TTX1100SAA	Date: 6-30-90
Originator: HENRY LISERIO	

SITE SKETCH  
ABANDONED PLATING FACILITY  
BALCH SPRINGS, DALLAS COUNTY, TX

VAT INVENTORY FOR HI-TECH PLATING

VAT #	HEIGHT (FT.)	WIDTH (FT.)	LENGTH (FT.)	DEPTH* (FT.)	pH	VOLUME (GALS.)	DESCRIPTION OF CONTENTS
1	4.5	3	10	3	13	673.2	clear liquid
2	4.5	3	10	4.5	1	1009.8	soapy greenish color liquid
3	4.5	3	10	4.5	7	1009.8	soapy greenish color liquid
4	4.5	3	10	0	-	0.0	empty
5	4.5	3	10	0	-	0.0	empty
6	4.5	3	10	4.5	12	1009.8	dark foamy liquid
7	4.5	3	10	3	2	673.2	dark foamy liquid
8	4.5	3	10	1	0	224.4	dark foamy liquid
9	4.5	3	10	4.5	0	1009.8	dark foamy liquid
10	4.5	3	10	4.5	11	1009.8	dark foamy liquid
11	4.5	3	10	4.5	13	1009.8	dark foamy liquid
12	4.5	3	10	4.5	10	1009.8	dark foamy liquid
13	4.5	3	10	4.5	4	1009.8	dark foamy liquid
14	4.5	3	10	1	10	224.4	dark foamy liquid
15	3	1.5	6	3	13	202.0	rinse water
16	4	3	10	4	5	897.6	dark liquid
17	4	4	8	0.1666	6	39.9	dark liquid
18	5	3	9.5	0.25	10	53.3	dark liquid
19	6	3	12	5.5	7	1481.0	dark liquid
20	6	3	12	5.5	10	1481.0	dark liquid
21	6	3	12	5.5	0	1481.0	dark liquid
22	6	3	12	3	0	807.8	blue foam liquid
23	6	3	12	5.8	1	1561.8	dark liquid
24	6	3	12	3	12	807.8	dark liquid
25	6	3	12	5.8	13	1561.8	dark liquid
26	6	8	12	0.5	14	359.0	da

VAT INVENTORY FOR HI-TECH PLATING

VAT #	HEIGHT (FT.)	WIDTH (FT.)	LENGTH (FT.)	DEPTH* (FT.)	pH	VOLUME (GALS.)	DESCRIPTION OF CONTENTS
27	6	8	12	0.5	14	359.0	dark liquid
28	6	3	12	0	-	0.0	dark liquid
29	6	3	12	0	-	0.0	dark liquid
30	6	3	12	6	7	1615.7	dark liquid
31	6	4	12	6	14	2154.2	dark liquid
32	6	3	12	3	13	807.8	dark liquid
33	5	3.5	10	2	7	523.6	labeled as hood 1
34	5	4	10	0.1	4	29.9	empty
35	5	4	10	4.8	2	1436.2	labeled as H2O ambient
36	5	3.5	10	4.8	5	1256.6	Al dip yellow ambient
37	6	4	10	0.1	6	29.9	H2O ambient label
38	5	3	10	4.8	0	1077.1	DEO x sc592
39	5	3	10	2	9	448.8	h2o
40	5	5	10	4	6	1496.0	etchant labeled
41	5	5	10	3	12	1122.0	SOAK Sk1003 140180
42	6	5	10	5.8	0	2169.2	lined with plastic
43	6	5	10	5.8	0	2169.2	lined with plastic
44	6	5	10	2	0	748.0	dark liquid
45	6	4	10	5.8	0	1735.4	green liquid
46	6	4	10	5.8	1	1735.4	dark liquid
47	6	4	10	5.8	13	1735.4	dark liquid
48	6	5	10	5.8	13	2169.2	white crystals on side/brn liq
49	6	10	10	0.5	14	374.0	dark soapy green liquid
50	6	5	9	5.8	0	1952.3	dark soapy green liquid
51	6	5	9	5.8	0	1952.3	dark green liquid
52	6	4	9	5.8	0	1561.8	dark liquid
53	6	5	9	5.8	14	1952.3	dark liquid
54	6	4	9	5.8	13	1561.8	dark liquid

AIR MONITORING RESULTS  
HI-TECH PLATING FACILITY

INSTRUMENT	SPECIES	LOCATION	READING
HNU Photoionization	VO	Inside whse.	0.1 ppm
Explosimeter	O2, LEL	Inside whse.	21%, 0.0
Draeger tubes	acid vapors	Inside whse.	2-5 ppm
Draeger tubes	CN	Near north vats	2.4 mg/M3
MIRAN Infared Analyz	CN	Near north vats	2-5 ppm
MIRAN Infared Analyz	CN	Above vat #48	5-8 ppm
Draeger tubes	CN	Above vat #48	2-4 ppm
MIRAN Infared Analyz	CN	Near middle vats	0 ppm



Page 1 of 5  
TDD#: T06-9002-35

**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/1545/ W

**Comments:** Front entrance to building with "No Tresspassing" signs erected by Fire Dept.

**1**

---

---

---



**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/ 1555/ E

**Comments:** Sanded portion of parking lot where leak occurred.

**2**

---

---

---



Page 2 of 5

TDD#: T06-9002-35

**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/1605/NW

**Comments:** Sanded area near south wall where leak occurred.

**3**



**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/1610/W

**Comments:** South wall corroded by leaking vats.

**4**



Page 3 of 5

TDD#: T06-9002-35

**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/ 1605/ W

**Comments:** Green discoloration in area where leak occurred.

**5**



**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90 / 1610/ NE

**Comments:** Corrosion in concrete caused by leaking material.

**6**



Page 4 of 5

TDD#: T06-9002-35

**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/ 1622/ E

**Comments:** Drainage area along north side of building, pH of standing liquid was neutral (6-7).

7



**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/ 1635/ SW

**Comments:** Openings in north building wall caused by corrosive materials.

8



Page 5 of 5

TDD#: T06-9002-35

**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/ 1638/ SE

**Comments:** Drums of HCl located on west end of site.

**9**



**Photographer / Witness**

Liserio/ Yank

**Date / Time / Direction**

2-28-90/ 1639/ N

**Comments:** Labeling on containers located outside of building.

**10**



**ecology and environment, inc.**

1509 MAIN STREET, DALLAS, TEXAS 75201

---

Unused Photographs & Negatives  
Abandoned Plating Facility  
Balch Springs, Dallas County, TX  
TDD# T06-9002-35  
PAN # TTX1100SAA

**POLREP #1**

**I. Hi-Tech Plating Facility  
2017 Peachtree  
Balch Springs, TX**

**Date:** 3/4/90  
**From:** Tom Yank/Henry Liserio  
**To:** Pat Hammack, Region VI-ERB  
**Subj:** Hi-Tech Plating Facility  
**Polrep:** POLREP #1

**II. BACKGROUND**

**Response Authority:** CERCLA- Site Assessment  
**NPL Status:** Not applicable

**III. INCIDENT INFORMATION**

**Situation**

On February 28, 1990, at approximately 14:30 hours, TAT conducted a site assessment at the Hi-Tech Plating Facility located at 2017 Peachtree in Balch Springs, Texas. The property is owned by Mr. Edwin Brown of Troup, Texas. The facility was leased to Mr. Rodney Gist, who operated a metal plating facility. The facility ceased operation in early February of this year.

The site assessment was conducted in response to a citizen's report of acids or other materials leaking from the site into the nearby drainage areas. Upon arrival at the scene, TAT observed sanded material near the south wall of the site and along a pathway leading to a drainage ditch on the southeast corner of the site. Dead vegetation was observed in the drainage area. TAT also observed a green discoloration near the sanded material and that portion of the concrete foundation was corroded by the sanded south wall. Twelve drums labeled as containing hydrochloric acid(10 of the drums were full) were located outside of the building near the west wall. The bottom portion of the north wall was corroded which suggested that leaks had occurred previously at the site. Signs were posted near the site door by the Balch Springs Fire Department declaring the site as hazardous. TAT contacted Bob Grant, Balch Springs Fire Marshal, for information on the site. The site is readily accessible from the nearby roadway, Peachtree street, and is surrounded by occupied residences and businesses located less than 200 feet from the site building.

According to Mr. Grant, a leak of an acidic material had

occurred about a week ago. The material had leaked from a vat used in the plating operation, out of the building, across the parking lot, and into the drainage ditch. Approximately 54 vats containing various types of highly acidic and basic materials were located in the building. Some of the vats were observed by the fire department officials to be leaking. Local officials also have encountered young trespassers who have entered the building through an opening in the sheet metal wall which was corroded by the leak. Mr. Grant informed TAT that the site also has been investigated by the Texas Water Commission and EPA RCRA officials for substantial discharges into the drainage system of wastes containing cyanides and heavy metals. According to Mr. Grant, the site owner was in the process of receiving bids for the cleanup actions at the site from several environmental firms. Mr. Grant also informed TAT that the site owner was very responsive and cooperative in assisting city and state officials in trying to remedy the situation, and was unaware of the poor operating procedures of the tenant.

#### B. Actions Taken

TAT inventoried each of the 54 vats by measuring the following parameters; the physical dimensions of the vats, the approximate volume of liquids in each vat, and the pH of each vat. The pH of the liquids in the vats, measured with pH indicator strips, ranged from 0 to 14. Several vats containing highly acidic materials (pH of 0-2) were located adjacent to vats containing highly basic liquids (pH of 12-14) with no separation between the vats. Several of the vats were almost full with minimal freeboard(less than 4 inches). A large percentage of the vats were in poor shape with visible corrosion. Several of the vats were leaking their contents onto the floor. The total volume of the acidic liquids(pH of 0-4) contained in the vats was 28,000 gallons, and the total volume of the basic materials(pH of 9-14) was 20,000 gallons.

TAT took samples from three of the vats containing basic liquids. The samples were checked for cyanides using silver nitrate reagents. Two of the samples were confirmed as containing at least 50 ppm of cyanides using the reagent test( a positive sample is confirmed by no change in color of the sample when adding the reagent). One of the vats confirmed as containing cyanides was located adjacent to a vat containing highly acidic materials.

TAT conducted air monitoring inside the building with the following instruments: HNU photoionization unit, explosimeter, MIRAN infrared analyzer; and draeger tubes for HCN, cyanides, acids, and HCl. The MIRAN instrument consistently detected HCN vapors ranging from 5 to 8 ppm near the vats located on the northern end of the building(near the vats confirmed as containing cyanides).

The acid draeger tubes detected approximately 3 to 5 ppm of total acids in the ambient air of the building, and 3-6 ppm of cyanides above the headspace of several of the vats.

Upon completion of the site assessment, the site owner was informed by the OSC of the need for immediate stabilization actions at the site. The site owner then contracted EmTech Environmental Services to take the following actions the following morning on March 3, 1990: redike and repair the leaking vats, cover several of the vats with visqueen for vapor suppression and to prevent further leaks, move the drums located outside the building into the building. The site owner also contacted the local police department to provide extra security at the site to prevent locals from entering the building.

#### **Future Plans**

TAT and the OSC will continue to monitor the situation via the telephone and by conducting on-site monitoring of the PRP removal activities. The site owner is planning on contracting a firm to take immediate remediation actions at the site within the next few days.

#### **Key Issues**

The main immediate threat to the environment and the public health and welfare was the leaking vats and easy access to the drums located outside the building. The large amounts of strongly acidic and basic materials located adjacent to each other, the poor condition of the vats, and the presence of cyanides in several vats and in the ambient air pose an immediate and substantial threat to the nearby residents and businesses.

**OSC:** Patrick Hammack

**TAT:** Tom Yank/ Henry Liserio

**Status of case:** Open

H. L. Lewis

Originator

## RECORDS OF COMMUNICATION

Conversation with:

Name Steve Brown

Company Site owner of Hi-Tech

Address Troup, TX

Phone (214) 442-7107

Subject Site assessment at Hi-Tech facility

Date 3 / 1 / 90

Time 1300 AM/PM

Originator Placed Call

Originator Received Call

W.O. NO. \_\_\_\_\_

Notes:

Talked with Mr. Steve Brown, relative of Mr. Edwin Brown, property owner of facility. Mr. Brown not there, but will be in office tomorrow.

File \_\_\_\_\_

Follow-Up-Action: \_\_\_\_\_

Tickle File \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

\_\_\_\_\_

Follow-Up By: \_\_\_\_\_

\_\_\_\_\_

Copy/Route To: \_\_\_\_\_

\_\_\_\_\_

Originator's Initials HL

H-Luzero  
Originator

## RECORDS OF COMMUNICATION

Conversation with:

Name Paul Cooper

Company TWC

Address Duncanville, TX

Phone (214) 298-6171

Subject Site assessment at Hi-Tech facility.

Date 3 / 1 / 90

Time 1520 AM EM

Originator Placed Call

Originator Received Call

W.O. NO. \_\_\_\_\_

Notes: Received call from Mr. Cooper, who conducted site investigation previously. Site operator was Reggie Gist, may be still operating in new location at Forney, TX. Mr. Cooper informed TAT that sewer line from facility was cut-off due to high cyanide and metals entering the municipal treatment plant. Site investigated by ERA RCRA, Everett Spencer (644-6475) RCRA official -

File \_\_\_\_\_

Follow-Up-Action: \_\_\_\_\_

Tickle File \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

\_\_\_\_\_

Follow-Up By: \_\_\_\_\_

\_\_\_\_\_

Copy/Route To: \_\_\_\_\_

\_\_\_\_\_

Originator's Initials

AJL

H. Lisenre  
Originator

## RECORDS OF COMMUNICATION

Conversation with:

Name Edwin Brown

Company Site owner

Address #

Troup, TX

Phone (714) 842-3107

Subject Site assessment at Hi-Tech Plating

Date 3 / 2 / 90

Time 830 AM/PM

Originator Placed Call

Originator Received Call

W.O. NO.

Notes: Talked with Mr. Brown about site assessment.

Purpose of visit is to assess the immediate threat and integrity of cuts containing waste. Mr. Brown requested to talk directly with OSC or EPA official. Informed Mr. Brown that ~~you are~~ we are a representative and consultant for EPA, and not actually an employee of EPA. Informed Mr. Brown that the purpose of visit was only to assess the problem to evaluate whether further action is required. Mr. Brown informed THAT that he's currently taking bids from contractors on cleaning up the site.

File \_\_\_\_\_

Tickle File \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Follow-Up By: \_\_\_\_\_

Copy/Route To: \_\_\_\_\_

Follow-Up-Action: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Originator's Initials

A/1

## RECORD of COMMUNICATION - H. Lescano

Originator

 Telephone Direct

Location: \_\_\_\_\_

 Other: \_\_\_\_\_

Date 4.2.90

Time 900

DRAFT

Name Henry Bridges Pit Hammatt

Company EVA

Address Dallas TX

Phone 1-55-2270

Subject Hi-Tech Plastics

 Originator Placed Call Originator Received CallNotes: Ask OSC for TPA extension fill  
4-30-90 and to amend hours

PL

Follow-Up-Reason: \_\_\_\_\_

Ticket File: \_\_\_\_\_

Follow-Up By: \_\_\_\_\_

Cacy / Route To: recycled paper

ecology and environment

H. Liscio  
Originator

## RECORDS OF COMMUNICATION

Conversation with:

Name Pat Hammack

Date 4 / 9 / 90

Company EPA

Time 1130 AM/PM

Address

Dallas, TX

Originator Placed Call

Phone 655-2270

Originator Received Call

Subject Site assessment report

W.O. NO. \_\_\_\_\_

Notes:

Amend TDD to include final report with removal action report which will not conclude till mid-June.

HL

File \_\_\_\_\_

Follow-Up-Action: \_\_\_\_\_

Tickle File \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

\_\_\_\_\_

Follow-Up By: \_\_\_\_\_

\_\_\_\_\_

Copy/Route To: \_\_\_\_\_

\_\_\_\_\_

Originator's Initials HL

H. Liscario

Originator

## RECORDS OF COMMUNICATION

Conversation with:

Name Bob Grant

Date 3 / 1 / 90

Company Bulch Springs Fire Dept

Time 1230 AM/PM

Address \_\_\_\_\_

Originator Placed Call

Phone (214) 557-6000

Originator Received Call

Subject Site assessment at Abandoned Electroplating Facility

W.O. NO. \_\_\_\_\_

Notes:

Talked with Mr. Grant about proposed sampling mission at Hi-Tech Plating facility at 2017 Pachetree. Told him that OSE planned on entering building to look at walls and check out integrity. Also, take pH of soils and photo document. Gave info on TWC contact, that the facility was illegally dumping wastes into sewer line, sewer was cut off by city water dept. Owner abandoned facility around mid-January. TWC investigated the site previously.

File \_\_\_\_\_

Follow-Up-Action: \_\_\_\_\_

Tickle File \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

\_\_\_\_\_

Follow-Up By: \_\_\_\_\_

\_\_\_\_\_

Copy/Route To: \_\_\_\_\_

\_\_\_\_\_

Originator's Initials NL

E & E Job Number \_\_\_\_\_

Telephone Code Number \_\_\_\_\_

Site Name H-Tech Plating

2017 Peachtree

State/City Beth Springs, TX

TDD 06-9002-75

PAN -77X11005A7

SSID \_\_\_\_\_

Start/Finish Date Feb. 28, 1990 / 3-3-90

Book 1 of 1

06-9002-35 2-28-90 H-Tech Plating

1330 - Received call from Jim Stares, to do drive-by inspection of a plating facility (unnamed). Received anonymous citizen's report that abandoned electroplating facility was leaking unknown substances into drainage ditch and runways by site (Report received by Jim Stares, OSC EVA-BRS).

1400 - TAT Liscio, Project manager Tom Yank, Site Safety officer assign to conduct site assessment


1430 - Safety meeting: do not contact any substances, do only preliminary drive-by inspection. Proposed activities: do a visual inspection, photograph site, check pH of site drainage if observed.

1545 - TAT Liscio and Tom Yank arrive at site. Camera used for photography: Olympus OM6. Serial # 101992, Lens serial # Soligor F28, 3794623.

Photo #1 2W, Front entrance with company name "unsafe" as declared

by Jim

06-9002-35 Not taken H-Tech Plating



4

04-9002-35 2-28-90 Hi-Tech Hwy 04-9002-75 2-28-90 Hi-Tech Hwy

by Fire Marshal, Yank / Lissner

1600 - Photo #3, north drainage

area W, Yank / Lissner

Photo #4 - corroded bottom

portion of sick bldg on north side, S, Yank / Lissner

1600 - Drums of hydrochloric acid, caustic soda, cyanoborite  
Observed outside of ~~west~~<sup>west</sup> side

of bldg - Photo #5, drums located on east side of site,

E, Yank / Lissner (east side west side of site). Photo #6  
drums will labels, E

11 drums of HCl, 4 closed, two open) one drum of aluminum cleaner one drum of sodium hypochlorite (10%), one unlabeled drum, one empty 30 gallon drum labeled as NaCN.

East correction - done by H. Lissner on 2-28-90


1610 - Photo #7, sand beam material used to stop leak

Mar 1990 -

5

Prin Sketch

(55 gal plastic drums)



Mar 1990

06-9002-35 2-25-90 H-Tech  
from south side of bldg., E,  
Yank/Licerco, Photo #8 - Green  
stained area on parking lot by  
sanded area, E - Yank/Licerco  
Photo #9 - Sanded material by  
south side of building to stop  
potential or past leaks, NW.  
Photo #10 - Close-up of concrete  
corroded by some past leak by  
sanded material, NE / Yank/Licerco

1b20- Call Staves at EPA office  
Leave message to call back -

1b22- Private citizen informs  
that that business has been  
out of business for approximately  
6 weeks. Spencer and Taylor of  
EPA have been to site to  
do site inspection - Fire dept.  
officials have been onsite and  
inspected the inside of bldg.

Citizen also reported that

Numerous water discharge violates

operator for metals and cyanide

1b30- Call fire dept. officials

May friend


06-9002-35 2-28-90 H-Tech  
Fire Chief will arrive at site  
to look at site with TAT-  
1b35- Talk with Paul Williams  
and Bob Grant of Balch Springs  
Fire dept. Property owner =  
Mr. Brown (not operator).  
2000 gal (2 tanks), one 3000  
gal of cyanide. One tank of  
HCl used, tanks filled -  
Sand material put out by Fire  
dept. HCl tank leaked through  
tank and went out of bldg  
to drainage area - Leaks  
from bldg. have been  
detected before at bldg.  
during operation - Approximate  
80% of tank fullled - Eight  
inches of precipitate, on bottom  
of tank Mr. Brown has  
contracted removal companies  
to conduct a possible site  
removal action - Three weeks  
ago natural operation shutdown  
1b35- Tanks have leaked at  
a frequent time  
May friend

06-9002-75 2-28-98 Hi-Tech

1650 - Photo #11, corroded sand and  
material, N.

1655 - Reports of teenage trills  
in bldg., readily accessible.  
Approximately 66 units located  
on site.

1700 - TAT takes pH reading  
with pH indicator strips  
and pH pen #696705 -



06-9002-75 2-28-98 Hi-Tech

1710 - pH of inside drain, HCl  
drum, pH = 6.3 with pH pen  
All readings along no-flow end  
taken with pH paper

1715 - Photo #12, houses west  
of site, W - York/Linco


Fire chief departs site after  
informing TAT of site history.

1730 - pH of drainage near strand  
area on SNE corner of site  
is 7.0 with pH pen.

1735 - TAT departs site. Attempts  
to reach OSC are futile.

1805 - Arrive at warehouse with  
equipment.

1815 - Depart warehouse after unloading  
equipment and materials.



06-9002-353-1-90Hi-Tech Plating06-9002-353-1-90Hi-Tech Plating

1030 - TAT H. Lizerio and T. York met with OSC Hammack to discuss site. Explain to OSC that material from site to nearby pathways as informed by and Fire Marshal Bob Grant re's of site to OSC.

Quests we conduct the Dangerous activities. Conduct deed Zto land owner, contact town and city officials of site

assessment, enter site and conduct a possible drum/but sampling mission, pH testing of soils, and screening of wastes located on the site.

1230 - call Bob Grant, Bach Springs Fire Dept. Notified him of proposed site assessment. Gave name of site owner, Edwin Brown, Troup, TX (214) 842-3107. TWC contact, Paul Cooper, Duncanville, TX - Abstract # 1564, Sec # 651564 355101 30000. Will meet us at site at 1000 hours.

1245 - Called site owner, Edwin Brown - Alex Lewis

Mr. Brown won't be in office till tomorrow morning. Discuss purpose of visit with relative, Steve Brown, and notified him of concerns regarding site.

Mr. Brown will notify Edwin Brown of proposed visit as soon as possible -

1300 - Prepare safety plan for sampling mission. Will use Haz Cat kit to check for cyanides.

1310 - Park called Appraisal (Tax-Assessor) and verified that site owner is Edwin Brown. Abstract # same as before.

1510 - Received call from Paul Cooper, TWC. Informed TAT that site operator was Reggie Gist, of <sup>Reggie</sup> <sub>3710</sub> may have relocated to Forney, TX. Industries located in area have water drainage shutdown due to high levels of cyanide, zinc, and other metals in water treatment influent exceeding plant capacity.

1540 - Depart office to warehouse Alex Lewis

06-9002-35 3-1-90 Hi-Tech Plating 06-9002-35 3-2-90 Hi-Tech Plating  
to load up equipment) need to wait 800 - TAT H. Hisenc, Project Manager,  
for truck to arrive at office.

1630 - Arrive at warehouse to load up truck (Hisenc and Yank) and Gary Dry, Haz Cat / Sampling  
with equipment for assessment. Coordinator meet at site <sup>Proposed</sup>  
1800 - Arrive back at office after <sup>3-2-90</sup> warehouse. Try to contact  
loading truck with equipment. Site owner, Edwin Brown, will  
call back later. Proposed activities

- Haz cat vat wastes, inventory  
and identify sick wastes inside  
building, take pH readings of  
sick wastes, conduct air monitoring,  
photograph / VCR the building  
wastes. Safety meeting: Entry  
into building and all activities  
inside building are level B  
with Surveyor, neoprene boots,  
hard hats. Watch out for liquids  
(do not contact liquids - Watch  
for slip/fall hazards, overhead  
hazards.)

\$15 - Call Edwin Brown. Mr. Brown  
requested that he talked with  
OSC directly instead of TAT.  
Informed TAT that he has been  
in contact with EPA RCRA  
They knew

06-9002-75 3-2-90 Hu-Tech Plating 06-9002-35 3-2-90 Hi-Tech Platings  
 officials, TWC, and city fire dept. to conduct HWU / explosivesmeter and  
 TAT Licensis informed Mr. Brown of droger tube readings. HWU used  
 relationship with EPA between TAT <sup>Instrument</sup> 3-2-90 EPA TAT #1, Serial  
 (consultant relationship). Dergers # <sup>#</sup> calibrated with isobutylene

to talk with OSC - will request gas, read 10 ppm at 9.7 span setting  
 that OSC contact him at later day. with 11.7 probe. Preacher Pmmp <sup>#</sup>

. 900 - Depart to site (Yank, his wife - 607926 - checked for leaks, no leaks  
 and Dry).

930 - Arrive at site. OSC's Hammack and Mullins onsite with Yank, Licensis, and Dry. OSC calls E. Brown to talk with PRP to discuss situation. OSC Hammack advises Mrs. Brown of emergency situation of site, acid spills, the Superfund act, the purpose of visit, the environmental threat to nearby residents, and authority

950 - of ERB Branch.

1000 - Bob Grant arrives at site. Advises OSC of past actions taken by state and city officials.

1030 - TAT Dry and Yank enter EZ in Level B, Licensis is backup in Level B. Dry and Yank

Mdry Licens

1045 - Grant / Hammack tour site.

Grant informed osc that city crews investigated with sand a spill which occurred a week ago. Big received by Mrs. Brown for cleanup sheet metal repaired at building face) kids were run out by fire dept who gained access through opening in sheet metal. Several plates in area have been targeted by Dallas Water District due to large discharges of metals and cyanides. Site owner was unaware of the operators business operations. Fire marshal had reports of chemical dumping on the soil behind facility (Batch Springs Marshall) Ddry Licens

06-4002-75 3-2-90 Hi-Tech

Hispanic labor force was working indoors without respirators, air has odor of HCl as witnessed by Fire Marshal. Also, fire marshals received complaints of odors in area. Operator has declared bankruptcy according to fire Marshal Grant. EPA RCRA contact Everett Spear 655-6475. Fire Marshal said that operator began around 2-86 and expanded since initial operation.

Operator departed site by 2-1-90.

HCl drums labeled: Pioneer Chemi

Inc., 100 N-Sam Houston, Missouri

TX 75149, 283-1042 -

TXD94228871 is RCRA

number 816 Brown Inds Waxahachie

75165. Site Operator Reggie Gist

452-bl-2580, 6351 Underbilt,

Dallas, TX 75214. Fire Marshal

has informed OSC that sewer has been

disconnected Dec. 1989 and that

locals vandalizing the buildings-

Operator is operating in Forney, TX

according to Fire Marshal, Plsg.

Reg Gist

06-4002-35

3-2-90 Hi-Tech

may be located by Cox Industrial employees. Building previously used by Fibro-Lay. Electrical company may be shutting power off at 24 Forney Industries, Terrell, TX. The fire dept. used wooden bung driven into one vat to stop leakage. Fire Marshal estimates 1000 persons, counting local industrial workers.

Actually, wooden bung put in by 1100- Air Monitoring. Results of initial entry:

Instrument	readings	location
HNU	<0.2 ppm units	throughout bldg.
explosimeter	-218 Oz	throughout bldg.
" "	no readings on LEL reading	
Acid dragger tape	2-5 ppm (20 strokes)	near middle of bldg.

HCl dragger no reading near south vats

Cyanide dragger 2-4 mg/m<sup>3</sup> near north vats

strokes for HCl, CN- tubes was 10-

Miran 1-B, 2-5 ppm of HCl

near north vats # 40-48. Instrument

zeroed outside of building in

fresh air. Miran 1B-2 readings


Reg Gist

06-0602-35      3-2-40      Hu-Tech  
taken again near north vents;  
instrument zeroed outside  
in fresh air 5-8 ppm vents  
using HCN Library. Instrument  
was calibrated using internal  
calibration program. Readings  
near south/middle row of vents  
were below 0 ppm of HCN units.

1230 - Minim 1B readings taken again near north cuts, still 5-6 ppm HCN units. Dragger tubes for cyanide over vat # 48 indicate a red stain of 2-4 ppm <sup>negative</sup> 3-210 mg/l (1.8-3.6 ppm) for cyanides. Dragger tube for hydrocyanic acid was no detection in same location. Three HCN dragger tubes taken at 10 strokes each with no detection. Second CN- dragger also no detection at 10 strokes - three more CN- dragger indicate no detection indicated in middle of area near middle vat section -

— My friend

06-4002-75      3-2-90      Hitech  
Site Sketch at inside bldg.



06-9002-353-2-90Hi-Tech06-9002-353-2-90Hi-Tech

<u>Unit #</u>	<u>Height</u>	<u>Width</u>	<u>depth</u>	<u>pH</u>	<u>length</u>	<u>width</u>	<u>height</u>	<u>depth</u>	<u>pH</u>	<u>length</u>
1	4.5'	3.0'	3	13	10'	23	3'	6'	12	12'
2	"		4.5	1		26	8'		full	13
3	"		4.8	2		27	8'		full	14
4	"		empty	-		28	3'		6"	14
5	"		empty	-		29	3'		6"	-
6	"		full	12		30	3'		empty	7
7	"		2/3 full	2		31	4'		empty	7
8	"		1	0		32	3'		full	14
9	"		full	0		33	3.5'	5'	1/2 full	13
10	"		full	11		34	4'	5'	2'	7
11	"		full	13		35	4'	5'	full	2
12	"		full	10		36	3.5'	5'	full	5
13	"		full	4		37	4'	6 1/2'	1 1/2"	4
14	"		full	10		38	5'	5'	full	0
15	3'	1.5	full	13		39	3'	5'	2'	9
16	4'	3.0	full	5		40	5'	5'	4'	6
17	4'	4'	2"	7		41	5'	5'	3'	12
18	5'	3'	3'	4	10'	42	5'	6'	full	0
19	6'		full	10		43	5'		full	0
20	"		full	7		44	5'		2'	>14
21	"		full	10		45	4'		full	4
22	"		1/2 full	0		46	4'		full	1
			Key Limer						Ply Limer	

<u>06-9002-35</u>		<u>3-2-90</u>	<u>Hi-Tech</u>	
<u>Unit #</u>	<u>Height</u>	<u>Length</u>	<u>width</u>	<u>pH</u>
47	6'	10'	4'	13
48		↓	8'	13
49			10'	14
50	9'		6'	0
51			5'	0
52			4'	0
53			5'	14
54			4'	13
Unit #	<u>description</u>	<u>Unit #</u>	<u>description</u>	
1	clear	12	—	
2	soggy	17	—	
3	—	18	—	
4	—	19	—	
5	foam dark	20	—	
6	dark	21	—	
7		22	blue foam	
8		23	dark	
9		24	dark	
10		25	dark	
11		26	—	
12		27	—	
13	—	28	—	
14	rinse	29	—	
15	—	30	—	
After turn				

<u>06-9002-35</u>		<u>3-2-90</u>	<u>Hi-Tech</u>
<u>Unit #</u>	<u>description</u>	<u>Unit #</u>	<u>description</u>
31	dark	43	lined plastic
32	dark	44	dark
33	—	45	green
34	empty	46	dark
35	H <sub>2</sub> O ambient	47	dark
36	Al dip yellow ambient	48	dark
37	H <sub>2</sub> O ambient	49	white crystalline
38	Deo. & SCS 50 ambient	50	dark green
39	H <sub>2</sub> O	51	dark green
40	etchant	52	
41	soak SK 1003	53	
42	Lined plastic	54	
1245	Yank collects samples in test tubes from vats 40, 48, 49. The pH of all vats taken with pH indicator strips. Yank uses Haz cut kit, checks pH to make sure above H <sub>2</sub> O, adds reagent for cyanide Haz cut results: Vat # 40, 3 drops of ROD and one drop AgNO <sub>3</sub> . results in slight color change to Lt. brn. Vat # 48, 1 drop of AgNO <sub>3</sub> and		

06-9002-35      3-2-90      Hi-Tech      06-9002-35      3-2-90      Hi-Tech  
 ROD results in no color change with OSC/Gazda and lawyers for  
 13 drops still no color change - EPA, Dif to accompany liberatio.  
 No color change indicates to EPA building.  
<sup>higher</sup> cyanide present. Unit #49 545- Meeting conducted with OSC's  
 has same results which also indicates presence of cyanide  
 above 50 ppm - Summary of air monitoring results -  
Drager tubes: CN<sup>-</sup>, 2-4 mg/m<sup>3</sup> above unit #49; otherwise no readings detected in general breathing area - HCl, HCl, after discussing the threats posed drager tubes indicated no readings by the site, OSC and C. Gazda in breathing area or near units - agree that an emergency Total acid - 2-3 mg/m<sup>3</sup> near units and breathing areas - removal action is warranted

1400- Site assessment activities concluded for today. Minor IB-2 readings ranged from 4.0-4.5 ppm. Highest reading 5-8 ppm was above the north units.

1430-Crew takes lunch.

1500-Crew departs site to meet OSC Mullins and Hammack to discuss results of site assessment response

After Lorraine

Hammack, Mullins, Gazda, Greg Fife, David Gray, Kim Turnbaugh of Criminal Investigation Division for EPA, and 2 EPA lawyers. Film of activities at site shown by OSC's to other officials present at the meeting, After discussing the threats posed by the site, OSC and C. Gazda agree that an emergency removal action is warranted at the site. Plans are made to contact owner of the steel for immediate actions at the site. Otherwise, ERCS will be mobilized to the site to take necessary actions at the site.

15- Report EPA building to warehouse to unload supplies. Talk with RSO C. Fountain of situation, and Chris Dowd

After dinner

06-9002-35

3-2-90

Hi-Tech

- IB15 - 6. Dry and Mr. Liserio depart 145- Arrive at warehouse to pack up van and equipment. Henry Liserio only that at warehouse. Depart to office to pick up supplies and safety information.

06-9002-35

3-3-90

Hi-Tech Plating

- 900 - called Pat Hammack, OSC requests that we meet him at site at 930 hours to discuss plans. Called Bob Grant, Fire Marshal, left message with fire station that we would be at the site to do possible removal actions. OSC will try to contact site owner to request action on his part and inform him of the need for quick stabilization action required to remedy immediate hazards posed by site wastes. Package sampling materials for personnel monitoring. (MCUF filters / impingers, NaOH for cyanides). Silica gel tubes for inorganic acids.
- 960 - Depart to site to meet OSC
- 140 - Arrive at site. PRR, Mr. Henry Lewis

06-9002-35

3-3-90

Hi-Tech

06-9002-35

3-3-90

Hi-Tech

Edwin Brown, has contacted EM-Tech and <sup>they</sup> were located, Listerio, Canada  
 Tech and ~~they~~ <sup>they</sup> 3-3-90 Dallas Environmental was same as before on  
 to take stabilization actions. Previous days.

at site are Pat Hammock, Edwin 15 - Crew (EM-Tech, Dallas Environmental)  
 Brown, Chip Day, Response manager TAT, and OSL depart site-TAT  
 for EM-Tech, 4 employees of TAT to go to office to leave off  
 EM-Tech, and one Dallas Enviro equipment.

Services employee. The crew is 200 - TAT arrives at office  
 working in Level 1 to take actions. Equipment and SCBA's offloaded  
 Actions taken by contractors - 300 - TAT departs office to whose do  
 Visqueen over cyanide tanks, drums continue offloading of equipment  
 from outside building moved inside, and supplies.

leaks have been repaired and 200 - TAT Listerio departs whose  
 stabilite. Mr. Brown contacted for home, Future monitoring  
 police dept. to provide extra actions are pending upon OSC decision  
 security for site.

1100 - OSC advises Mr. Brown that  
 actions need to be taken within  
 next week to instigate removal  
 action, the formal communication  
 paperwork he will receive describing  
 EPA's past communications with

him. Photo #1-3, E, Visqueen  
 over cyanide tanks, Listerio -

Photo #4 1 N, area where drums

John Lewis

May 1  
John Lewis

# **TARGET SHEET**

**SITE NAME:** HIGH-TECH PLATING

**CERCLIS I.D.:** TXD174127407

**TITLE OF DOC.:** TECHNICAL DIRECTION DOCUMENT T06-9002-35  
AND AMENDMENTS A & B

**DATE OF DOC.:** March 12, 30, 1990 and April 27, 1990

**NO. OF PGS. THIS TARGET SHEET REPLACES:** 3

**SDMS #:** 174766-174768      **KEYWORD:** 91.03

**CONFIDENTIAL ?**  **MISSING PAGES ?**

**ALTERN. MEDIA ?**  **CROSS REFERENCE ?**

**LAB DOCUMENT ?**  **LAB NAME:** \_\_\_\_\_

**ASC./BOX #:** \_\_\_\_\_ **RAW ANALYT. DATA ?**

**CASE #:** \_\_\_\_\_ **SDG #:** \_\_\_\_\_

**COMMENTS :** \_\_\_\_\_  
These documents have been moved to records 174766, 174767 and  
174768. The documents contain confidential business information that  
has been refiled in Contractor Confidential.